

## General PSE Notes

1. Contact [maprequest@pse.com](mailto:maprequest@pse.com) for updated gas maps of area.
2. Maintain a minimum 1' vertical separation when crossing gas mains or services.
3. Maintain a minimum 3' horizontal separation when running parallel to gas mains or services.
4. If HP is encountered, please contact PSE PI Inspector before working near HP gas mains: Glenn Huden, 206-396-4159, [glenn.huden@pse.com](mailto:glenn.huden@pse.com)
5. Coordinate with PSE Customer Construction Services at 1-888-321-7779 and a PSE project manager for relocation of gas mains and services as needed.
6. Locate and protect all gas facilities in the field.